

Comprehensive Facility 2019 Re-Assessment Presentation













SUMMARY OF 2015 ASSESSMENTS

- Full Assessments
 - Jr. High School Campus
 - Thomas Edison Elementary
- Roof and HVAC
 - W.E. Chalmers Elementary
- Roof Only
 - Administration Building
 - Robert E. Lee Elementary



INTRODUCTION AND METHODOLOGY

Establishing Priorities

This assessment provides information on the condition of the facilities; from entire buildings to individual building components. These can range from structures to finishes, and include all other components such as mechanical and electrical systems, individually and as a complete assembly. The assessment also provides information on the replacement cost and life expectancy of each component.

Prioritization begins with the assessment findings which place each component in one of four urgency categories ("CAT"):

- CAT I Indicates that the need is immediate, or "critical" in terms of the item itself.
- CAT II Indicates that the need is "trending critical" with repair or replacement necessary within 12 months.
- CAT III Indicates that repair or replacement is "necessary" within 2 to 5 years.
- CAT IV Indicates that repair or replacement is "recommended" within 3 to 10 years

These categories having been established, priorities are then assigned according to the condition of use within a hierarchy of the following group of criteria:

- A: Safety if the deficiency is not addressed/resolved health and safety are at risk.
- B: Necessity if the deficiency is not addressed/resolved vital tasks cannot be accomplished
- C: Efficiency if the deficiency is not addressed/resolved operating efficiency or cost effectiveness is diminished.

With these determinations made, priorities are established according to the relative importance of the category/criteria combination (which introduces the dimension of time) thus, the evaluations may be sorted according to CAT I-A being the highest, and CAT IV-C being the lowest, with various gradations in between.

Overall Category



I-A II-A I-B II-B III-A III-B I-C II-C IV-A IV-B III-C IV-C

Top Priority

Low Priority

INTRODUCTION AND METHODOLOGY

Facility Condition Index (FCI)

It is important to note that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussions in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur. Other factors such as historical significance, community sentiment, and enrollment trends will create additional variables for replacement consideration.



As you move through this report you will notice the graphic below indicates a facility condition percentage based on our assessment of repairs needed and the cost of deficiencies. One of these charts will be included for each building or site assessed. To figure this percentage, we divided the total cost of repairs needed by the total replacement cost of the building or site.

Facility Condition Index (FCI) %

<5%	6-10%	11-20%	21-30%	31-50%	51-65%	>65%
Best	Good	Average	Below	Poor	Very Poor	Replacement
			Average			Candidate

Following each assessment will be a chart indicating the campus, building, description of deficiencies, and an estimated cost of those deficiencies with a priority level (as described on page 8) that introduces the level of urgency in which the repairs should be made.



SUMMARY OF 2019 RE-ASSESSMENT

PART 1

Administration Building
Junior High School Campus
Thomas Edison Elementary


PART 2


High School Robert E. Lee Elementary W.E. Chalmers Elementary



2019 RE-ASSESSMENT – ADMINISTRATION BUILDING

		2015 Deficiencies		2019 Deficiencies		Renovation Cost Estimate (\$)	2019 Replacement				
Facility	Subject	Description	2019 Pricing with Inflation since 2015 Assessment	Description	Pricing as of June 2019	2019	Low	High	Priority Rating	Condition Index	Recommendation
	Site	Roof repair was completed in the year of 2017 as we understand it.	0	Exterior Window Replacement	600,000						Renovation Recommendation based on:
	93,802sf			Site Improvements	160,000						Mid-Range "III-B" Priority Rating
	(2.15 acres)			Upgrade Interior Finishes	350,000	4 000 000				Below	"Below Average" Condition Index
Administration	Building			Upgrade HVAC, Security, Electrical & Infrastructure	128,000	1,369,000	4,895,750	5,874,900	III-B	Average	
	17,874 sf			Upgrade Doors & Hardware	85,000						
				Asbestos Abatement	46,000						
	Total					1,369,000	4,895,750	5,874,900			









2019 RE-ASSESSMENT – JUNIOR HIGH SCHOOL (1 of 3)

		Exterior Accessibility Compliance	103,250	No new deficiencies	0						Replacement Recommendation based on:
	Site	Widen Fire Lanes & Turn-arounds	169,500							Replacement	"Replacement Candidate" Condition Index
	141,553 sf (3.25 acres)	Exterior Drainage Inlets & Downspouts	28,250			1,657,000	2,300,000	2,760,000	II-B	Candidate	
		Paving Replacement	1,356,000								
		Exterior Window Replacement	2,980,000	Toilet Room Accessibility Compliance	150,000						Replacement Recommendation based on:
		Electrical Reliability, Efficiency & Safety Upgrade	1,500,000	Asbestos Abatement	250,000						"Replacement Candidate" Condition Index
	Main Building 78,830 sf	Replace Roof	1,750,000			7,133,000	20,000,000	24,000,000	II-A	Replacement Candidate	Most Building Systems have Surpassed Normal Life Expectancies
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Replace Rooftop HVAC Units	275,000								High "II-A" Priority Rating
		Light Fixture LED Upgrade	226,000								
Gainesville Junior High		Café Area Exterior Structural Column Repair	2,000								
School	Old Gymnasium	Lower Locker Room Conversation to Storage	60,000	• Interior Finish Upgrade	250,000						Renovation Recommendation based on:
		Roof Decking Structural Interior Board Repair	25,000	Gymnasium Floor Replacement	100,000					Below	Historic Value Despite High "II-B" Rating
	10,645 sf	Repair/Replace Exterior Canopies	25,000	Asbestos Abatement	25,000	563,000	2,750,000	3,300,000	II-A	Average	"Below Average" Condition Index
		Electrical Repairs	8,000								
		Lower Level Exterior Window Replacement	70,000								
		Exterior Window Replacement	100,000	No new deficiencies	0						Renovation Recommendation based on:
		Basement Electrical Repairs	60,000								Mid-Range "III-B" Priority Rating
	Auditorium/ Music Building.	Basement Renovation	150,000			795,000	5,500,000	6,600,000	III-B	Average	"Below Average" Condition Index
	20,453 sf	Replace Rooftop HVAC Units	250,000								
		Accessibility Compliance	15,000								
		Interior Finish Upgrade	220,000								
	Total		1 11								








2019 RE-ASSESSMENT – JUNIOR HIGH SCHOOL (2 of 3)

	Special Services Building 2,875 sf	Exterior Window Replacement Fire Alarm System Repair Replace Roof Replace Rooftop HVAC Units Testing for Asbestos Exterior Masonry Repair Electrical Repairs	260,000 15,000 100,000 65,000 2,000 6,000 5,000	No new deficiencies	0	453,000	718,750	862,500	II-B	Very Poor	Replacement Recommendation based on: "Very Poor" Condition Index Inadequate Size Deteriorating Building Systems Inflexible Design
Gainesville Junior High School (Continued)	Competitive Gymnasium 14,590 sf	Exterior Window Replacement Entry Cleaning and Painting Roof Repair Concession Bar Accessibility Compliance Condensate Line Exterior Masonry Repair Electrical Repairs	85,000 2,500 13,000 5,500 2,500 3,000 4,500	Interior Finish Upgrade	150,000	116,000	3,650,000	4,380,000	III-B	Good	Renovation Recommendation based on: Mid-Range "III-B" Priority Rating "Good" Condition Index
	Field House 4,900 sf	Replace Roof Enlarge Locker Rooms Replace Flooring Renovation - Walls, Floors, Ceilings, Finishes Test for Asbestos Replace Rooftop HVAC Units Electrical Repairs	75,000 150,000 75,000 245,000 2,000 65,000 47,000	No new deficiencies 0		659,000	1,230,500	1,476,600	II-A	Very Poor	Replacement is recommended due to: "Very Poor" Condition Index Undersized Locker Room, Laundry Room & Equipment Storage Inadequate Size Inflexible Design
	Total					1,228,000	5,599,250	6,719,100			









2019 RE-ASSESSMENT – JUNIOR HIGH SCHOOL (3 of 3)

	Weight Room 2,400 sf	Interior Finish Upgrade Accessibility Compliance Replace Rooftop HVAC Units	26,000 14,000 30,000	No new deficiencies	0	70,000	600,000	720,000	IV-A	Average	Renovation Recommendation based on: Low-Range "IV-A" Priority Rating "Average" Condition Index
Gainesville	Maintenance Building 4,060 sf	Replace Exterior Windows & Overhead Doors Cleaning and Minor Repairs	75,000 85,000	Replace Rooftop HVAC Units Replace Roofing	50,000	230,000	1,025,000	1,230,000	IV-C	Below Average	Renovation Recommendation based on: Low-Range "IV-C" Priority Rating
Junior High School		Demo & Remove Cooling Tower	8,000	No new deficiencies	0						Replacement Recommendation based on:
(Continued)	Central Plant	Demo & Remove Old Equipment	70,000								High Range "II-A" Priority Rating
	Building	Replace Roof	35,000			148,000	700,000	840,000	II-A	Below Average	Inadequate Size
	2,800 sf	Main Electrical Switchgear Fire Rated Enclosure	10,000								Deteriorating Building Systems
		Light Fixture LED Upgrade	25,000								• Inflexible Design
	Total				448,000	2,790,000	2,790,000				









2019 RE-ASSESSMENT – THOMAS EDISON ELEMENTARY

		Accessibility Compliance	60,000	No new deficiencies	0						Renovation Recommendation based on:
		Fire Lane Compliance and Radius Re-W0rk	175,000								
	6 74	Fire Hydrants & FDC Code Compliance	65,000								
	Site 511,300 sf 11.74 acres	Play Structures & Area Accessibility Compliance	250,000								
	11.74 acres	Replace Site & Exterior Lighting	30,000								
		Tie in Downspouts to Drains	8,000								
		Regrading & Cleaning Area Drains	67,000								
		Replace Roof	1,120,000	No new deficiencies	0						Renovation Recommendation based on:
		Repair Canopy	3,000								High-Range "I-A" Priority Rating
Thomas Edison		Replace Rooftop HVAC Units	900,000								"Average" Condition Index
Elementary School		Interior Life Safety Study	32,000			3,124,000	17,500,000	21,000,000	I-A	Average	Most Building Systems have Surpassed Normal Life Expectancies
		Replace Fire Alarm System	45,000								
		Electrical Receptacle Code Upgrade	60,000								
	Main Building 69,249 sf	Light Fixture LED Upgrade	214,000								
	65,245 \$1	Replace Emergency Lighting & Exit Sign Battery Backups	54,000								
		Telephone Backboard Fire Proof Repair and Relocate	4,000								
		Electrical Panel Repair & Replacement	16,000								
		Repair and Relocate Electrical Services	13,000								
		Repair/Replace Mechanical Room Boards & Isolators	8,000								
	Total					3,124,000	17,500,000	21,000,000			









2019 RE-ASSESSMENT - HIGH SCHOOL

		2015 Deficiencies		2019 Deficiencies		Renovation Cost Estimate (\$)		lacement imate (\$)			n Recommendation
Facility	Subject	Description	2019 Pricing with Inflation since 2015 Assessment	Description	Pricing as of June 2019	2019	Low	High	Priority Rating	Condition Index	
		No Deficiencies Cited		Complete New Parking Lot Striping	45,000						Renovation Recommendation based on:
	Site			ADA corrections near Gym	35,000	530,000			III-A	Dont	Overall site is well maintained
	8.2 Acres			Determine Parking Lot Paving Need West of Stadium	300,000	330,000			III-A	Best	Paving improvements limited to resurfacing and stripping
				Resurface Band Hall practice area	150,000						
Gainesville		Re-caulk Masonry, Roofing, Sidewalks and Building	24,000	• Paint	135,000						Replacement Recommendation based on:
High School		Replace roof-top HVAC Units	816,000	Flooring repair/replacement of existing carpe	12,000		43,470,000	51,840,000			Roof-top HVAC Equipment have Surpassed Normal Life Expectancies
	Main Building			Gym Lighting Upgrades	25,000						Roof-top HVAC Equipment R-22 Refrigerate Ceases to be Manufactured Dec. 31,2019
	162,000 SF			Misc. Paint, Floor, Ceiling Upgrade at Training	65,000	1,185,500			II-A	Best	• Most Building Systems have Surpassed Normal Life Expectancies
				Shingle Replacement	25,000						
				Flooring Upgrades at Gym Locker Rooms	21,500						
				HVAC Test and Balance	62,000						
	Total					1,715,500					









2019 RE-ASSESSMENT - ROBERT E. LEE INT. SCHOOL

	Site 10.5 Acres	No Deficiencies Cited		Restriping existing Pavement Sealants around Building Repair asphalt	20,000 25,000 8,500	53,500			III-A	Good	Renovation Recommendation based on: Overall site is well maintained Paving improvements limited to resurfacing and stripping
Robert E. Lee Intermediate School	Main Building 58,668 sf	Minor Roof Repair	6,000	Remove VWC, patch/Float walls and Paint Flooring repair/replacement of existing carpe Lay in Ceiling replacement (10% assumed) Roof repair at known leaks VCT at Gym and new Markings Coiling Door/HM Door replacement at Gym HVAC Test and Balance Fire Panel replacement Roof is at "end of life" Epoxy at Lab Tables in lieu of Plam*	110,000 101,000 15,000 25,000 15,800 10,500 24,000 12,500 800,000 16,000	1,135,800	15,840,000	18,774,000	III-A	Good	Renovation Recommendation based on: Overall building is well maintained Most of the Deficiencies are Cosmetic Roof has Surpassed Normal Life Expectancy and should be replaced
	Total					1,189,300					








2019 RE-ASSESSMENT – W.E. CHALMERS ELEMENTARY

	Site	Not included in 2015 Comprehensive Facility Assessment Report	Restriping existing Pavement Sealants around Building and paint	20,000 35,000	55,000			III-A	Good	Renovation Recommendation based on: Overall site is well maintained Paving improvements limited to stripping
W.E. Chalmers Elementary School	Main Building 77,720 sf	Not included in 2015 Comprehensive Facility Assessment Report	Remove VWC, patch/Float walls and Paint Flooring repair/replacement of existing carpe Patch and repair drywall Lay in Celling replacement (10% assumed) PLAM replacement at Classrooms Replace some failing seals/storefront VCT at Gym and new Markings Coiling Door replacement at Gym HVAC Test and Balance Roof is at "end of Life"	155,000 132,000 5,000 20,000 35,000 7,500 15,800 10,500 31,000 1,400,000	1,811,800	20,900,000	24,870,000	II-A	Good	Renovation Recommendation based on: Overall building is well maintained Most of the Deficiencies are Cosmetic Roof has Surpassed Normal Life Expectancy and should be replaced
	Total				1,866,800					







TOTAL COST OF 2019 DEFICIENCIES (PART 1 & PART 2)

Part 1

 Total Renovation Cost
 \$16,317,000.00

 Replacement Cost (Low)
 \$61,335,000.00

 Replacement Cost (High)
 \$73,044,000.00

Part 2

Total Renovation Cost \$4,771,600.00 Replacement Cost (Low) \$80,210,000.00 Replacement Cost (High) \$95,484,000.00

Part 1 & 2 Total

 Total Renovation Cost
 \$21,088,600.00

 Replacement Cost (Low)
 \$141,545,000.00

 Replacement Cost (High)
 \$168,528,000.00



TOTAL COST OF 2019 DEFICIENCIES

D	Facility	P rio rity	Condition Index	RepairCost	Replacem entCost Low	Replacem entCost High
1	Adm in istration Site & Building	III-B	Below Average	\$1,369,000	\$4 , 895 , 750	\$5 , 874 , 900
2	Jr.High Site	II-B	Replacem ent Candidate	\$1 , 657 , 000	\$2,300,000	\$2,760,000
3	Jr.High Building	II-A	Replacem ent Candidate	\$7,133,000	\$20,000,000	\$24,000,000
4	Jr.HighOblGym	II-A	Below Average	\$563,000	\$2,750,000	\$3,300,000
5	Jr.High Auditorium	II - B	Average	\$795,000	\$5,500,000	\$6,600,000
6	Jr.High SpecialServices	II - B	Very Poor	\$453,000	\$718 , 750	\$862,500
7	Jr.H igh Com petitive Gym	III-B	Good	\$116 , 000	\$3,650,000	\$4,380,000
8	Jr.High Field House	II-A	Very Poor	\$659,000	\$1,230,500	\$1,476,600
9	Jr.High W eightRoom	IV -A	Average	\$70 , 000	\$600,000	\$720,000
10	Jr.H igh Maintenance Building	IV-C	Below Average	\$230,000	\$1,025,000	\$1,230,000
11	Jr.High CentralPlant	II-A	Below Average	\$148,000	\$700,000	\$840,000
12	Edison Site & Building	I-A	Average	\$3,124,000	\$17,500,000	\$21,000,000
13	High SchoolSite	III-A	Best	\$530,000	\$43,470,000	\$51,840,000
14	High SchoolBuilding	II-A	Best	\$1,185,500		
15	Robert E. Lee Site	III-A	Good	\$53,500	\$15,840,000	\$18,774,000
16	Robert E. Lee Building	III-A	Good	\$1 , 135 , 800		
17	W E.Chalmers Elementary Site	III-A	Good	\$55,000	\$20,900,000	\$24,870,000
18	W E.Chalmers Elementary Building	II-A	Good	\$1 , 811 , 800		
				\$21,088,600	\$141,080,000	\$168,528,000



REPLACEMENT ORDER BASED ON CONDITION INDEX

ID	Facility	P rio rity	Condition Index	Repair Cost	Replacem entCost	Replacem entCost
	racuity	LINITY	Condition index	керашсовс	Low	High
2	Jr.H igh Site	II - B	Replacem ent Candidate	\$1 , 657 , 000	\$2,300,000	\$2 , 760 , 000
3	Jr.High Building	II - A	Replacem ent Candidate	\$7,133,000	\$20,000,000	\$24,000,000
		•		\$8,790,000	\$22,300,000	\$26,760,000
6	Jr.High SpecialServices	II-B	Very Poor	\$453,000	\$718 , 750	\$862,500
8	Jr.High Field House	II - A	Very Poor	\$659,000	\$1 , 230 , 500	\$1 , 476 , 600
				\$1,112,000	\$1,949,250	\$2,339,100
1	Adm in istration Site & Building	III-B	Below Average	\$1,369,000	\$4 , 895 , 750	\$5 , 874 , 900
4	Jr.High Old Gym	II-A	Below Average	\$563 , 000	\$2,750,000	\$3,300,000
10	Jr.H igh Maintenance Building	IV-C	Below Average	\$230,000	\$1 , 025 , 000	\$1,230,000
11	Jr.High CentralPlant	II-A	Below Average	\$148 , 000	\$700 , 000	\$840 , 000
				\$2,310,000	\$9,370,750	\$11,244,900
5	Jr.H igh Auditorium	II-B	Average	\$795 , 000	\$5,500,000	\$6,600,000
9	Jr.High W eightRoom	IV –A	Average	\$70 , 000	\$600 , 000	\$720 , 000
12	Edison Site & Building	I - A	Average	\$3,124,000	\$17,500,000	\$21,000,000
				\$3,989,000	\$23,600,000	\$28,320,000
7	Jr.H igh Com petitive Gym	III-B	Good	\$116,000	\$3,650,000	\$4,380,000
15	Robert E. Lee Site	III-A	Good	\$53,500	\$15,840,000	\$18 , 774 , 000
16	Robert E. Lee Building	III-A	Good	\$1 , 135 , 800		
17	W E.Chalmers Elementary Site	III-A	Good	\$55,000	\$20,900,000	\$24,870,000
18	W E.Chalmers Elementary Building	II-A	Good	\$1 , 811 , 800		
				\$3,172,100	\$40,390,000	\$48,024,000
13	High SchoolSite	III-A	Best	\$530,000	\$43,470,000	\$51,840,000
14	High SchoolBuilding	II-A	Best	\$1 , 185 , 500		
				\$1,715,500	\$43,470,000	\$51,840,000





QUESTIONS AND ANSWERS